



**SPARE PARTS FOR  
ASIAN VEHICLES**



# Spare parts for Asian vehicles from the thermal management expert

Rely on our expertise in products and services for your customers with Asian vehicles. Experience our wide range of products for yourself!

Behr Hella Service is well known as THE expert for engine cooling and vehicle air-conditioning. The quality of our Behr Hella Service is characterised by reliability, fitting accuracy and a long service life. This quality is based on BEHR's OE expertise, which is incorporated directly into our products. We offer these products as quality parts for a variety of passenger cars, light commercial and commercial vehicles. With more than 6,000 spare parts, our product range serves vehicles of every age, class and make. Of course this also includes a large selection for Asian vehicles.

In order to provide you with a brief overview of the Behr Hella Service programme for these vehicle types, we have compiled a selection of the more than 1,000-part product range for Asian vehicles on the following pages.

You can find the complete range from Behr Hella Service in the corresponding catalogues as well as in TecDoc.





	GETZ	OE NO.*	I30	OE NO.*	TUCSON	OE NO.*
<b>Production period</b>	2005 –		2007 – 2011		2004 – 2009	
<b>Compressor</b>	8FK 351 273-061 8FK 351 273-071 8FK 351 273-081 8FK 351 273-111	977011C100 977011C150 977011C250 9770117000 9770125200	8FK 351 273-471  8FK 351 273-481  8FK 351 273-491  8FK 351 340-041	977012H000 977012H040  977012H100 977012H140  977012H200 977012H202 977012H240  977012L300 977012L302 977012R340	8FK 351 273-181  8FK 351 273-201  8FK 351 273-211	977012C100 977012D100  977012D600  977012D700
<b>Condenser</b>	8FC 351 302-651  8FC 351 302-281  8FC 351 302-291  8FC 351 302-301  8FC 351 318-071	976061C000  976061C100  976061C300  976061C350  976061C200	8FC 351 303-211  8FC 351 303-221  8FC 351 318-701	976062H000 976062H010  976062H600  976062L600	8FC 351 302-361	976062E000
<b>Filter-dryer</b>	8FT 351 198-691	9780217000 9780225000 978532H000	–	–	8FT 351 200-711	978012E000
<b>Blower unit</b>	8EW 351 040-521	971121C000	8EW 351 040-541	971132L000	–	–
<b>Expansion valve</b>	8UW 351 239-501	976041C050 976041C100	–	–	8UW 351 239-551	976262E100
<b>Fan, engine cooling</b>	8EW 351 034-661  8EW 351 041-391	253801C100  253801C150 253801C160	8EW 351 043-191  8EW 351 043-351  8EW 351 043-361  8EW 351 043-371	253802H150  253802H050  253802H151  253802H600	8EW 351 034-511  8EW 351 043-051	253802E250  253802E010
<b>Interior heat exchanger</b>	–	–	8FH 351 315-711	971382L000	8FH 351 315-241 8FH 351 315-701	971382E100 971382E150
<b>Coolant radiator</b>	8MK 376 754-491  8MK 376 754-511  8MK 376 762-001  8MK 376 762-011  8MK 376 762-021	253101C200  253101C600  253101C100  253101C150  253101C300	8MK 376 754-521  8MK 376 763-321  8MK 376 763-711	253102H000  253102L600  253102H050	8MK 376 745-621  8MK 376 763-211  8MK 376 763-651  8MK 376 763-671  8MK 376 763-681  8MK 376 763-691  8MK 376 763-331	253102E550  253102E100  253102E101  253102E400  253102E500  253102E800  253102E700 253102E711
<b>Blower controller</b>	9ML 351 321-461	970351C010 9703525000 9703525010	5HL 351 321-481  9ML 351 321-371	9711138000 971792D000 972351E000 9723526000  971283K000	5HL 351 321-411  5HL 351 321-421  9ML 351 321-381  9ML 351 321-451	971791F200  971792D200  970353A000 970353D000 971282D000  971282D200 971282D210
<b>Water pump</b>	8MP 376 801-181	2510027000 2510027100	8MP 376 807-541	2510027400	8MP 376 802-431  8MP 376 802-761  8MP 376 801-181  8MP 376 807-541	2510023001 2510023002  2510037102 2510037202  2510027000 2510027100  2510027400

For further details, please also refer to information from BEHR HELLA SERVICE catalogues, TecDoc and information from the manufacturer. This list is not exhaustive and may contain errors. See TecDoc or the HELLA catalogues for other products from the lighting, electrics / electronics ranges. \* OE numbers are for comparative purposes only.

## OUR RANGE

## Kia



	CEED	OE NO.*	RIO II	OE NO.*	SORENTO	OE NO.*
Production period	2006–2009		2005–2011		2002–2009	
Compressor	8FK 351 273-471 8FK 351 273-481 8FK 351 273-491 8FK 351 340-041	977012H000 977012H040 977012H100 977012H140 977012H200 977012H202 977012H240 977011H300 977012L300 977012L302 977012R340	8FK 351 340-051 8FK 351 340-061	977011G000 977011G300 977011G300AS 977011G311	8FK 351 273-441 8FK 351 273-301	977013E000 977013E050 977013E600
Condenser	8FC 351 318-701 8FC 351 318-441 8FC 351 318-451	976062L600 976061H000 976061H600	8FC 351 303-111 8FC 351 303-131	976061G000 976061G300	8FC 351 302-701 8FC 351 303-061	976063E000 976063E001 976063E600 976063E601
Filter-dryer	8FT 351 198-691	9780217000 9780225000 978532D000 978532H000	–	–	–	–
Fan, engine cooling	8EW 351 042-761 8EW 351 042-771 8EW 351 042-781 8EW 351 042-791	253801H050 253801H120 253801H250 253801H680	8EW 351 041-351 8EW 351 041-361 8EW 351 042-751	253801G050 253801G350 253801G000	8EW 351 034-641 8EW 351 034-501	977303E000 253803E600
Interior heat exchanger	–	–	8FH 351 315-681	971381G000	–	–

## Mitsubishi



	CARISMA	OE NO.*	LANCER VI	OE NO.*	PAJERO III	OE NO.*
Production period	1995–2006		2002–2007		1999–2006	
Condenser	8FC 351 037-351 8FC 351 303-521	CAB311B078 MB958166 CAB311B102A MR460269	8FC 351 304-231 8FC 351 304-441 8FC 351 318-051	MN134204 MN151100 MN134204 MN151100 MR500441 MR218428 MR360276	8FC 351 304-081	MN123332 MR513110
Filter-dryer	8FT 351 195-521	MB813589 MB869217 MB869218 MR175422	8FT 351 200-371	MR500065	8FT 351 197-151	AW337382 MB918516 MR117107
Coolant radiator	8MK 376 718-541	MB925637	8MK 376 770-321	MR968856 MR968858	8MK 376 753-661	1350A155 MR968289
Water pump	8MP 376 801-211 8MP 376 800-791	MD313301 MD309756 MD346790	8MP 376 800-791 8MP 376 803-081 8MP 376 807-501 8MP 376 800-211	MD309756 MD346790 MD975644 MD975913 MD977311 MD978552 MD979313 MD979395 MN980134	8MP 376 805-151 8MP 376 805-181	ME996789 ME996790
Water-pump kit	8MP 376 809-801 8MP 376 813-841		–	–	–	–

# Toyota



	COROLLA	OE NO.*	YARIS	OE NO.*	RAV4 II	OE NO.*
Production period	2002 –		1999 – 2005		2000 – 2006	
Compressor	8FK 351 340-781  8FK 351 340-881  8FK 351 125-221	883101A580 883201A481 883201A550  8831002270 8831002340 883101A620  8831042250 8831042260	–	–	–	–
Condenser	8FC 351 310-191  8FC 351 300-541  8FC 351 307-771	8845002240 8845002250 8845012260  8845013030 8845002150 8845013031  8846012540	8FC 351 300-261  8FC 351 302-201  8FC 351 304-221	884500D020 8846052020  8846052010  8846052040	8FC 351 302-111  8FC 351 318-711	8846042070  8846042060 8846042090
Filter-dryer	8FT 351 197-701	8847447010	8FT 351 197-701	8847447010	8FT 351 197-701	8847447010
Expansion valve	–	–	8UW 351 239-721	–	–	–
Coolant radiator	8MK 376 753-721 8MK 376 753-731 8MK 376 773-631 8MK 376 773-641 8MK 376 775-441	1640022160 164000N030 164000N031 1640021140 164000D220 1640021160 1640021180	8MK 376 718-421  8MK 376 773-471 8MK 376 773-481 8MK 376 781-141	164000J010 1640023080 1640023100  1640021070 1640021060 164000N011	8MK 376 755-791	1640027060 1640027061
Water pump	8MP 376 803-701  8MP 376 803-031	1610009130 1610029095 1610029145 1610029175 1610029415  1610029155 1610029156 1610029195 1610029196	8MP 376 803-031  8MP 376 803-451 8MP 376 805-141	1610029155 1610029156 1610029195 1610029196  1610029115 1610009141 1610029125	8MP 376 803-701  8MP 376 803-111	1610009130 1610029095 1610029145 1610029175 1610029415  1610028040 1610028041

# Honda



	CIVIC VII	OE NO.*	ACCORD VIII	OE NO.*	CR-V II	OE NO.*
Production period	2001 – 2005		2003 – 2008		2002 – 2006	
Compressor	–	–	–	–	8FK 351 340-031	38810PNB006
Condenser	8FC 351 330-401	403712S1541 80110S5A003 80110S6A901 80110S6DG01	8FC 351 303-681	80110SEA003	8FC 351 318-061	80101SCAA01 80110S9A003
Coolant radiator	8MK 376 753-631 8MK 376 768-291 8MK 376 768-301	19010PMAE61 19010PMMA01 19010PMMA51	8MK 376 768-371	19010RAAA51	8MK 376 768-311 8MK 376 768-321	19010PNLG01 19010PNLG51
Water pump	8MP 376 802-251	19200PLMA01	8MP 376 807-441	19200RBB003 19200RBB013 19200RFE003	–	–

For further details, please also refer to information from BEHR HELLA SERVICE catalogues, TecDoc and information from the manufacturer. This list is not exhaustive and may contain errors. See TecDoc or the HELLA catalogues for other products from the lighting, electrics / electronics ranges. \* OE numbers are for comparative purposes only.

## Mazda



	2	OE NO.*	6	OE NO.*	PREMACY	OE NO.*
Production period	2007 –		2002 – 2008		1999 – 2004	
Compressor	–	–	–	–	8FK 351 103-021 8FK 351 103-031	B22B61K00 B25F6100A B25F61K00 C10061K00 GE9E61K00
Condenser	8FC 351 307-761 8FC 351 310-231 8FC 351 310-241	D4Y16148ZB D6Y16148Z DF7161480A	8FC 351 301-181  8FC 351 318-791	GJ6A61480B GJYA6148Z GJYA6148ZA  GS1D61480C GS1D61480D GSYD6148ZA GSYD6148ZC	8FC 351 301-091	B25SF61480 C10061480 C10061480A C10061480B L4800C100A
Filter-dryer	–	–	8FT 351 197-741	BBM461501 GJ6A61501 GJ6A61501A	8FT 351 197-071	BJ3D61500A BK2J61500A GE4T61500A GE9E61500
Charge air cooler	–	–	8ML 376 756-561	BBM461501 GJ6A61501 GJ6A61501A	–	–
Coolant radiator	8MK 376 753-641	ZJ3815200A	8MK 376 750-261 8MK 376 750-271 8MK 376 750-281 8MK 376 769-671 8MK 376 769-681	LF1715200 LF1715200A  LF2115200 LF2115200A  RF5C15200 RF5C15200A  L32715200 L32715200A  L32815200 L32815200A	8MK 376 769-621  8MK 376 769-631	FP8715200A FP8715200B FP8815200A FP8815200B  FP8515200A FP8615200 FP8615200B
Water pump	8MP 376 801-051 8MP 376 805-371	Y40115010 ZJ0115010A ZJ0115010B	8MP 376 801-721		8MP 376 800-781	8AG915010
Water-pump kit	8MP 376 811-861		–	–	–	–

## Suzuki



	SWIFT III	OE NO.*	LIANA II	OE NO.*	GRAND VITARA	OE NO.*
Production period	2004 – 2010		2001 –		1998 – 2005	
Condenser	8FC 351 304-431 8FC 351 303-491	9531063J00 9531062J00 9531062J10	8FC 351 309-121 8FC 351 310-761	9531054G01 9531054G11	8FC 351 303-781 8FC 351 318-781	1740069G00 1740069G01 9531065D20 9531065D21
Filter-dryer	8FT 351 200-391	9533963J00	–	–	–	–
Coolant radiator	8MK 376 756-531	1770062J00 1770063J00	8MK 376 773-021 8MK 376 773-031	1770054G00 1770054G10	8MK 376 724-661 8MK 376 773-001	1770077E00 1770077E20 1770052D10
Water pump	8MP 376 805-271	1740069G00 1740069G01	8MP 376 805-271  8MP 376 801-051	1740069G00 1740069G01	–	–

# Nissan



	ALMERA II	OE NO.*	MICRA III	OE NO.*	QASHQAI	OE NO.*
<b>Production period</b>	2000–2006		2003–2010		2007–	
<b>Compressor</b>	8FK 351 135-361 8FK 351 135-861	92600BN701 92600BN701	8FK 351 322-211  8FK 351 316-421	92600AX80A 92600AX80B 92600AX84B  2763000Q1M 2763000QAP	8FK 351 316-421  8FK 351 340-201  8FK 351 340-351	2763000Q1M 2763000QAP  92600JD700 92600JD70B 92600JD73A 92600JD74A 92600JD75A  92600BR00A
<b>Condenser</b>	8FC 351 302-521  8FC 351 038-581  8FC 351 304-651	92100BN900  92110BM400  92100BM407 92100BN307	8FC 351 307-781    8FC 351 303-231  8FC 351 303-251	92100AX800 92100AX801 92100AX80B  921009U20B 92100AY601  92100AY600	8FC 351 310-121  8FC 351 310-141  8FC 351 310-221	92100JD200 92100JD20A  92100JD500 92100JD51A  92100JD700 92100JD71A
<b>Fan, engine cooling</b>	–	–	8EW 351 043-701	21481AY610	–	–
<b>Charge air cooler</b>	–	–	8ML 376 760-671	14461AY600	8ML 376 746-601	14461BB30A 14461JD50A 14461JD50B
<b>Coolant radiator</b>	8MK 376 770-651  8MK 376 770-701  8MK 376 770-661	21410BM400 21410BM402  21410BN300 21410BN301  21460AV700	8MK 376 781-161	21410AY601 21410AY602 21410BC510	8MK 376 753-681  8MK 376 753-691  8MK 376 753-701	21400JD100 21400JD900  21400JD50B 21400JD51B  21400JD70A 21400JD71A
<b>Water pump</b>	8MP 376 803-341  8MP 376 803-391  8MP 376 800-511  8MP 376 800-611	210109F605  21010AD200 21010AD225 21010AD226  2101000QOE  2101000QAS 2101000QAT 21010BN700	8MP 376 800-511  8MP 376 800-611  8MP 376 805-281	2101000QOE  2101000QAS 2101000QAT 21010BN700  21010BX000	8MP 376 800-511  8MP 376 805-421	2101000QOE  210100000C 2101000Q0C
<b>Water-pump kit</b>	8MP 376 814-821  8MP 376 814-831  8MP 376 810-851		8MP 376 810-851  8MP 376 814-821  8MP 376 814-831		8MP 376 814-831	



For further details, please also refer to information from BEHR HELLA SERVICE catalogues, TecDoc and information from the manufacturer. This list is not exhaustive and may contain errors. See TecDoc or the HELLA catalogues for other products from the lighting, electrics / electronics ranges. \* OE numbers are for comparative purposes only.

Sales and other information available from:

**HELLA KGaA Hueck & Co.**

Rixbecker Straße 75  
59552 Lippstadt, Germany  
Tel.: +49 2941 38-0  
Fax: +49 2941 38-7133  
Internet: [www.hella.com](http://www.hella.com)

**HELLA Limited**

Wildmere Industrial Estate  
Banbury, Oxon OX16 3JU  
Tel.: (01295) 225600  
Fax: 0800 7832571  
E-mail: [hella.sales@hella.com](mailto:hella.sales@hella.com)  
Website: [www.hella.co.uk](http://www.hella.co.uk)

**HELLA Ireland Limited**

Woodford Business Park  
Santry, Dublin 17  
Republic of Ireland  
Tel.: +353 (1) 8620000  
Fax: +353 (1) 8621133  
E-mail: [irlsales@hella.com](mailto:irlsales@hella.com)  
Website: [www.hella.ie](http://www.hella.ie)

© BEHR HELLA SERVICE GmbH, Schwäbisch Hall  
922 999 133-476 xx/12.12/0.7  
Printed in Germany



Sales and other information available from:

**HELLA Asia Singapore Pte Ltd**  
Regional Headquarters Asia Pacific  
Independent Aftermarket  
2 International Business Park  
#02-12 The Strategy  
Singapore 609930  
Tel: +65 6854 7300  
Fax: +65 6854 7302  
E-mail: [singapore@hella.com](mailto:singapore@hella.com)  
Internet: [www.hellaasia.com](http://www.hellaasia.com)

© BEHR HELLA SERVICE GmbH, Schwäbisch Hall  
922 999 133-477 xx/12.12/0.1  
Printed in Germany